

Material review report

MATERIAL REVIEW LOCAL PILOT · PUBLIC NIGERIAN DOCUMENT EVALUATION

Material item	IOM Lagos BOQ · internal wall paint · public test
Intended use	Public-document test: internal wall paint, reviewer-selected satin finish. No live client decision or local availability claim.
Supplier	Dulux Trade · public document test
Selected product	Dulux Trade Vinyl Matt · DATA SHEET 411
Requirements / submission	Baseline v1 / Revision 1
Recorded by	Public document test reviewer · reviewer@material-review.local
Recorded at	10 October 2026, 16:42 WAT

Revise And Resubmit

Public-document evaluation only: selected satin finish conflicts with the submitted matt statement. This is not an IOM decision, supplier endorsement or a claim of current Nigerian product availability. Archived manufacturer page used to verify non-tile document comparison.

Findings and sources

CONFLICTS

Paint finish

Required: **Satin**Submitted: **matt**

The documented value differs from the approved requirement.

Requirement · Page 13

"INTERNAL WALL prepare and apply three coats of CAPLUX SATIN paint or any other of equal quality as approved by Architect or Client on:"

Document 9f53461c-e5c7-481a-8064-3ed3b480f358 · Source block d23a5481-2dd7-4d0a-b05a-5e5ad03ad6a7

Supplier · Page 1

"matt"

Document 90e4acd6-883b-4a84-8f5e-e8f03191864c · Source block ca7f0c0e-3ab0-4d65-9e6b-f2c9eb18c7ad

Review record

This report preserves the inputs, machine findings and reviewer corrections at the time of the recorded decision. It describes document evidence; it does not authenticate certificates or verify physical material quality.

Analysis fca8d00e-cbbf-43c1-b193-782a21b10101

Baseline b07d6909-a57c-418a-b8b1-61bf83fba525 · Submission 3d90add9-aeb2-44e7-a894-7a73a099c1e5

Model gemini-3.8-flash · Prompt materials-extraction-1.1.0 · Rules materials-1.2.0 · Parser document-parser-1.0